



IIIG02N005		A		REVISIONS	
ZONE	REV	DESCRIPTION	DATE	APPROVED	



- Notes:
- 1) For best accuracy, Oxygen measurements should be taken 2ft. below the surface and 3ft. from the wall.
 - 2) Measurement element surface should not be facing directly upward or downward. Sensor should be clocked to the 3 or 9 o'clock position as shown.

UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN INCHES. TOLERANCES ON: FRACTIONS DECIMALS ANGLES		CONTRACT NO.		 1550 W. Lindburg Dr. Slidell, LA 70458	
MATERIAL	DESIGNER	DRAWING NO.	DATE	DO SENSOR MOUNTING	REV
SPEC	PROJ. ENGR.	IIIG02N005	SCALE		A
FINISH	APPROVAL		NTS		