



REVISIONS				
ZONE	REV	DESCRIPTION	DATE	APPROVED

11G02N004 A



- Notes:
- 1) Sensor Material: Epoxy, Polyurethane, PVC, 316 SS
  - 2) Oxygen measurements should be take 2ft. below the surface and 3ft. from the wall.
  - 3) Measurement element surface should not be facing downward in order to avoid collecting air bubbles.

UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN INCHES. TOLERANCES ON: FRACTIONS DECIMALS ANGLES		CONTRACT NO.		 80 Whisperwood Blvd. Suite 107 Slidell, LA 70458	
MATERIAL		SIGNATURES		DO SENSOR OUTLINE & MOUNTING	
SPEC		DRAFTER		DRAWING NO. 11G02N004	
FINISH		CHECKER		SCALE NTS	
		DESIGNER		SHEET 1 of 1	
		PROJ. ENGR.		REV A	
		RELEASED			
		APPROVAL			